

Instruction for 6-3/4" Inner Cylinder that uses Type "A" or Type "B" motor (19" and 22" length)

We are pleased that we can continue supplying replacement parts for almost every barber pole that has been produced in the United States. Due to the very low volume of sales of some non-Marvy Barber Pole parts, we are now forced to do modifications to use standard Marvy parts to fit Koch and Paidar Barber Poles, which have not been produced in almost seventy years. We are committed to keeping barber poles spinning!

The 6-3/4" diameter inner cylinders for Koch and Paidar Barber Poles will now require a modification to the light fixture for the new replacement inner cylinder to fit and operate properly.

Please refer to the photo (below) of the top metal end of the inner cylinder and refer to the instructions below.



1. Remove (and save) the two white plastic finger screws on the ends of the cross strap.
2. Carefully twist clockwise on the strap to remove it from the metal end.
3. Disassemble the light fixture and replace the 3-1/2" strap with this new 5-3/4" strap, taking care to make sure that the 'top sticker' is facing to the top strap of the light fixture. If the pipe on your light fixture does not fit through the hole, filing the hole open may be required.
4. Reassemble the light fixture, replace the inner cylinder and connect the light fixture to the inner cylinder by reversing steps 2 and 1 above.

If you need assistance, please contact us at 870-972-5300
or customerservice@cachebeauty.com